





### Cup Square Bolts

Thread Size	Length (mm)	Part No. 	Part No. 
M10	16	318AR31-GA	318AR81-SS
	20	318AR32-GA	318AR82-SS
	25	318AR33-GA	318AR83-SS





### Cone Point Hex Head Set Screw

Thread Size	Length (mm)	Part No. 	Part No. 
M10	40	M10x40-CP-ZD	M10x40-CP-SS-A4
M12	40	M12x40-CP-ZD	M12x40-CP-SS-A4



### Hex Head Set Screw

Thread Size	Length (mm)	Part No. 	Part No. 
M6	20	M6x20-HS-GA	M6x20-HS-SS-A4
	25	M6x25-HS-GA	M6x25-HS-SS-A4
	30	M6x30-HS-GA	M6x30-HS-SS-A4
	35	M6x35-HS-GA	M6x35-HS-SS-A4
	40	M6x40-HS-GA	M6x40-HS-SS-A4
M8	20	M8x20-HS-GA	M8x20-HS-SS-A4
	25	M8x25-HS-GA	M8x25-HS-SS-A4
	30	M8x30-HS-GA	M8x30-HS-SS-A4
	35	M8x35-HS-GA	M8x35-HS-SS-A4
	40	M8x40-HS-GA	M8x40-HS-SS-A4
M10	20	M10x20-HS-GA	M10x20-HS-SS-A4
	25	M10x25-HS-GA	M10x25-HS-SS-A4
	30	M10x30-HS-GA	M10x30-HS-SS-A4
	35	M10x35-HS-GA	M10x35-HS-SS-A4
	40	M10x40-HS-GA	M10x40-HS-SS-A4
	50	M10x50-HS-GA	M10x50-HS-SS-A4
	60	M10x60-HS-GA	M10x60-HS-SS-A4
M12	25	M12x25-HS-GA	M12x25-HS-SS-A4
	30	M12x30-HS-GA	M12x30-HS-SS-A4
	35	M12x35-HS-GA	M12x35-HS-SS-A4
	40	M12x40-HS-GA	M12x40-HS-SS-A4
	50	M12x50-HS-GA	M12x50-HS-SS-A4
60	M12x60-HS-GA	M12x60-HS-SS-A4	
75	M12x75-HS-GA	M12x75-HS-SS-A4	

